DORAL MINERAL SANDS PTY LTD (DORAL)

KEYSBROOK MINERAL SANDS PROJECT

COMPLIANCE ASSESSMENT REPORT – AUDIT TABLE

Shire of Serpentine-Jarrahdale, Shire of Murray Development Approval

Dated: 18 October 2023

| 1.0 | FIRE MANAGEMENT PLAN | | | | | | | | |
|---------------|---|---|----------|-----------------|---|---------|---|--|--|
| Audit Code | Assessment Task | Timing | Complian | ce | Action | | Comments | | |
| | | | Yes / No | Date | Action Taken | Date | | | |
| 1.1 | Firebreaks | | | | | | | | |
| 1.1.1 | Mineral Sand Extraction Site | | | | | | | | |
| 1.1.1.1 | Install bare mineral earth trafficable firebreaks clear of all flammable material to a minimum of 4 metres wide and unlimited vertical clearance immediately inside all external boundaries of the mineral extraction area with all overhanging branches, trees, limbs etc to be trimmed back or pruned with a clear vertical axis over the firebreak. | Completed by the date shown in the local government fire control notice. | Yes | October 2023 | Firebreaks installed. Maintenance scheduled for November 2023 | Ongoing | Firebreaks are installed prior to 30 November annually | | |
| 1.1.1.2 | Install bare mineral earth trafficable firebreak to a minimum of 4 metres wide and unlimited vertical clearance externally around the bounded of mineral sand extraction areas where mining is in progress. | Completed by the date shown in the local government fire control notice. | Yes | October 2023 | Firebreaks installed. | Ongoing | Perimeter access tracks around all active mining and rehabilitation areas. Perimeter bunding in some areas also serves as impediment to fire spread. | | |



| 1.0 | FIRE MANAGEMENT PLAN | | | | | | |
|----------|--|--|----------|-----------------|---|---------|---|
| Audit | Assessment Task | Timing | Complian | се | Action | | Comments |
| Code | | | | | | | |
| | | | Yes / No | Date | Action Taken | Date | |
| 1.1.2 | Building Protection Zone | | - | - | | | 1 |
| 1.1.2.1 | A 30-metre wide building protection zone is to be installed around all operations, administrative, plant or other structures whether temporary or semi-permanent in accordance with the fire management plan. | Completed by the date shown in the local government fire control notice. | Yes | October 2023 | Building protection zones established. Maintained during reporting period. | Ongoing | Completed on lots with infrastructure. |
| 1.1.2.10 | Fences and sheds within the Building Protection Zone are to be constructed using non-combustible materials (e.g. colourbond iron, brick, limestone). | On Construction | Yes | October 2023 | Steel fencing used on site. Storage is via sea containers. | | Completed. |
| 1.2 | Significant Vegetation Area (Appro | x. 75 ha) | • | • | · | • | • |
| 1.2.1 | A trafficable firebreak 4 metres wide and unlimited vertical clearance is to be installed within 15 metres of the edge of the significant vegetation area. | Ongoing | Yes | October 2023 | Firebreaks established around conservation covenant areas. Maintained during reporting period. | Ongoing | Firebreaks are installed prior to 30 November annually |
| 1.2.2 | Firebreaks and building protection zones are to be installed. | Completed by the date shown in the local government fire control notice. | Yes | October 2023 | Firebreaks maintained during reporting period. | Ongoing | Firebreaks are installed prior to 30 November annually |
| 1.4 | Bushfire Risk Management | | | | | | |
| | Stockpiling of coarse mulch and vegetation from the site of mining operations will be restricted to stockpiles measuring 20 metres long by 6 metres wide and 3 metres high. | Ongoing | Yes | October 2023 | Mulch and vegetation stockpiles maintained to specification. | Ongoing | |
| | Each stockpile is to be cleared for 10 metres around it free of flammable material and is to be | Ongoing | Yes | October 2023 | Mulch and vegetation stockpiles maintained to specification. | Ongoing | |



| 1.0 | FIRE MANAGEMENT PLAN | | | | | | |
|-------------|--|---|-----------|-----------------|--|-------------------------------------|----------|
| Audit | Assessment Task | Timing | Compliant | ce | Action | | Comments |
| Code | | | | - | | - | |
| | | | Yes / No | Date | Action Taken | Date | |
| | located 20 metres from any standing vegetation. | | | | | | |
| 1.5 | Contacts | | | | | | |
| 1.5.1 | A list of names, telephone numbers and radio frequencies of earth moving plant that may be used in firefighting within the mine operation area to be provided to the Local Authorities. | As minimum annually, and as details change. | Yes | October 2023 | Contact details provided to Shires and local volunteer Fire Brigades. | Ongoing | |
| 1.6 | Brigade Familiarisation of site | | | | | | |
| 1.6.1 | Resident Manager will provide the local Bush Fire Brigade with details relating to access, firebreak, water supplies, equipment available and contact details. | Each year prior to summer wildfire season in October/ November | Yes | October 2023 | Invitations sent to Keysbrook and North Dandalup volunteer bush fire brigades for site visit on 17 th October 2023 | 17 th October 2023 | |
| Fire Manag | ement Plan Endorsed By: Refer to Co | mpliance Report 2013 | | | | | |
| Signature:_ | N/A | | | | | | |
| Date: | N/A | | | | | | |



| 2.0 | VISUAL MANAGEMENT PLAN | | | | | | |
|---------------|---|--|---------------|-----------------|--|---------|--|
| Audit Code | Assessment Task | Timing | Complian | ce | Action | | Comments |
| | | | Yes / No | Date | Action Taken | Date | |
| 2.1 | Views from Elliot Road, Hopeland | Road, Atkins Road an | d Westcott R | oad | | | |
| 2.1.1 | R1.1 — Weed clearance and supplementary planting in existing verge-side plantings | Prior to extraction operations on site. | Yes | October 2023 | Weed spraying and planting undertaken along Hopeland Road frontage in October 2017. Weed spraying completed October 2023. Maintenance ongoing. | Ongoing | |
| 2.1.2 | R1.2 — Planting of native tree and shrubs species. | Prior to extraction operations on site. | Yes | October 2023 | Native species used. Local area seed collection completed November – March 2016, and July – August 2017 Native vegetation shelter belt planted June 2018 parallel with Hopeland Road across Lots 31, 32, and 33. 600 Native seedlings were planted in Lot 202 adjacent to Elliot Road in 2022. | Ongoing | |
| 2.2 | Views from roads directly adjacer | t to extraction operati | ons | | | | |
| 2.2.1 | R1.3 — Creation of 2m high bunds from overburden and spoil material. Located between the excavation area and the development site boundary. | In accordance with operational staging. | Yes | October 2023 | Perimeter earthen bunds established adjacent to operational areas. | Ongoing | Topsoil bunds fronting Elliot road, northern end of Lot 57. |
| 2.3 | Views new extraction operations, | where extraction oper | ations are no | t directly ad | jacent to a road | | |



| 2.0 | VISUAL MANAGEMENT PLAN | | | | | | |
|---------------|--|--|----------|------------------|--|----------|--|
| Audit Code | Assessment Task | Timing | Complian | ce | Action | | Comments |
| | | | Yes / No | Date | Action Taken | Date | |
| 2.3.1 | R1.4 — 2 m high bunds do not disrupt general access and circulation of personnel. | In accordance with operational staging. | Yes | October 2023 | Perimeter earthen bunds established adjacent to operational areas. | Ongoing | |
| 2.4 | Where extraction operations occu | r adjacent to Westcott | Road | | | | |
| 2.4.1 | R1.5 — Where 2 m high bund not possible, provide a visually impermeable fence consisting of post and wire configuration, shade cloth, hessian or similar material. Colour of material to reflect tones of the landscape. | In accordance with operational staging. | Yes | October 2023 | 3m topsoil bunds fronting Westcott Road and Elliot road. | Ongoing | Topsoil bunds fronting Elliot road, northern end of Lot 57. |
| 2.5 | Plant buildings and structures | | | | | | |
| 2.5.1 | R1.7 — External colours of the site office, processing plant, water tanks workshops, lunchrooms to match Dulux colours PG1-H6, PG1-G6, PG1-F6, PG1-E6, PG1- E7, PG1-D7, PG1-B6, PG1-B7. | Prior to or on Installation of Structures on site. | Yes | October 2015 | Infrastructure coloured accordingly. | Complete | |
| 2.6 | Lighting | | | | | | |
| 2.6.1 | R1.8 — Lighting associated with the plant designed by qualified lighting engineer and meet Health and Safety Standards. | On Installation | Yes | November 2015 | Lighting design completed by competent persons. Light spill audit completed March 2019. | Complete | |



| 2.0 | VISUAL MANAGEMENT PLAN | | | | | | |
|---------------|---|-------------------------|--------------|-----------------|--|---------|--------------------------------------|
| Audit Code | Assessment Task | Timing | Complian | ce | Action | | Comments |
| | | | Yes / No | Date | Action Taken | Date | |
| 2.7 | Off-site commercial signage (exc | luding safety signage) | | | | | |
| 2.7.1 | R1.10 — Signage to meet the standards and approvals of local authority. | On Application | Yes | October 2023 | Signage installed as per requirements. | Ongoing | Complete & updated as required |
| 2.8 | Concerns expressed by neighbo | uring properties to the | south of the | extractive de | evelopment | ł | 1 |

| 2.0 | VISUAL MANAGEMENT PLAN | | | | | | |
|---------------|--|---|----------|-----------------|--|----------|-----------------------------|
| Audit Code | Assessment Task | Timing | Complian | ce | Action | | Comments |
| | | | Yes / No | Date | Action Taken | Date | |
| 2.8.1 | R1.11 — Vegetative buffer and overburden bunds along the southern boundary of the extractive development to be planted in accordance with Figure 6. | Vegetation to be planted prior to Extraction of operations on site. Bunding constructed in accordance with operational staging. | Yes | October 2023 | Trees planted. Maintenance and infill planting continues October 2016. In accordance with the Rehabilitation Management Plan. Infill planting undertaken on Southern Boundary in July 2017 Perimeter earthen bunds established adjacent to operations A further 7 ha of perimeter native vegetation planting completed in 2019 in accord with plan agreed with landowner. Planting of 189,181 of biodiverse native seedlings have been planted in Lot 300 and Lot 59. 25ha of Lot 300 has also been sown with local provenance native seed mix to enhance the native rehabilitation. During 2023 Infill planting occurred throughout the 75ha of native revegetation along the southern boundary, approximately 20,000 seedlings were planted in these areas. | Complete | |
| 2.9 | Key Performance Indicators and M | Ionitoring | • | • | | • | |
| 2.9.1 | Review success of Visual Management Plan (VMP) in accordance with key performance indicators in Part 5.2 of the VMP and produce visual management report. | Annually | Yes | October 2023 | Boundary assessment completed: • October 2023 | Ongoing | Assessment report attached. |



| 2.0 | VISUAL MANAGEMENT PLAN | | | | | | |
|---------------------|--|------------------------|-----------|-----------------|--|---------|---|
| Audit Code | Assessment Task | Timing | Compliand | ce | Action | | Comments |
| | | | Yes / No | Date | Action Taken | Date | |
| 2.9.2 | Monitoring visits to evaluate success of VMP | Bi-annually | Yes | October 2023 | Visual assessments are undertaken on ongoing basis in the course of environmental monitoring. Formal boundary assessment completed October 2023 | Ongoing | Formal October 2023 assessment report attached. |
| | gement Plan Endorsed By: Refer to (| Compliance Report 2013 | | | | | |
| Signature: Date: | N/A N/A | | | | | | |



| 3.0 | MOSQUITO MANAGEMENT PLAN | | | | | | |
|---------------|--|--|-----------|-----------------|--|---------|----------|
| Audit Code | Assessment Task | Timing | Complianc | e | Action | | Comments |
| | | | Yes / No | Date | Action Taken | Date | |
| 3.1 | Any depressions created within the extractive area, the ground surface will be filled or drained, where possible, to prevent the ponding of water, in conjunction with the outcome of the Rehabilitation Management Plan. | Ongoing | Yes | October 2023 | Continual water recovery from mine voids as part of operations. Mine voids promptly backfilled with sand and clay tailings in preparation for rehabilitation | Ongoing | |
| 3.2 | Storage containers capable of ponding water will be either discarded after use or stored in an inverted position (care will be taken to ensure that ponding does not occur in rubbish storage areas). | On cease of use. | Yes | October 2023 | No such storage containers routinely deployed on site. Ongoing practice of housekeeping. | Ongoing | |
| 3.3 | Inspect stagnant ponds within the extractive area filled with water for the presence of mosquito larvae. If larvae are detected, the Medical Entomology Branch of the Department of Health will be consulted on what actions should be taken. | After a significant rainfall event between the months of August to May. | Yes | October 2023 | No persistent stagnant ponds in active extractive area. | Ongoing | |
| 3.4 | During the induction process staff and contractors will be: | Induction of new staff and contractors | | - | - | | |
| | Made aware of the potential risk of mosquito borne disease and the high risk periods. | | Yes | October 2023 | Induction includes mosquito risks | Ongoing | |
| | Advised to wear long sleeved shirts and trousers, avoid going outside at sundown, and to use insect repellent. | | Yes | October 2023 | Site Standard. | Ongoing | |
| | Educated about the early symptoms associated with exposure to mosquito-borne | | Yes | October 2023 | Site standard to report all incidents and illness to supervisors. | Ongoing | |



| 3.0 | MOSQUITO MANAGEMENT PLAN | | | | | | |
|---------------|---|-----------------------|-----------|-----------------|---|----------|-----------|
| Audit Code | Assessment Task | Timing | Complianc | e | Action | | Comments |
| | | | Yes / No | Date | Action Taken | Date | |
| | arbovirus and will be instructed on the need to report any symptoms to a medical officer. | | | | | | |
| 3.5 | Insect repellent will be provided at work sites. | Ongoing | Yes | October 2023 | Insect repellent available to personnel | Ongoing | |
| 3.6 | On-site facilities will be screened and air conditioned. Lights will be fitted with yellow bulbs to discourage mosquitoes. | On Construction | Yes | October 2023 | Facility screened and air conditioned. Yellow bulbs fitted. | 27/10/15 | Completed |
| Mosquito Ma | anagement Plan Endorsed By: Refer to | o Compliance Report 2 | 013 | | | | |
| Signature: | N/A | | | | | | |
| Date: | N/A | | | | | | |



| 4.0 | COMMUNITY CONSULTATION FRAMEWORK FOR THE KEYSBROOK PROJECT | | | | | | | | |
|---------------|---|---|--|---|---|--|---|--|--|
| Audit Code | Assessment Task | Timing | Complian | ce | Action | | Comments | | |
| | | | Yes / No | Date | Action Taken | Date | | | |
| 4.1 | Sign – at Shire of Murray and Serpentine Jarrahdale Admin offices | Prior to commencement of operations at site | - | - | Advised by Shires sign not required. | - | | | |
| 4.2 | Public briefing | Beginning of each phase | - | - | Construction and Operational Phase Briefings held 2014, 2015 and 2016. Next public briefing will be for closure phase. | - | | | |
| 4.3 | Site visit – (in addition to the requirements to access the site detailed within any approved management plan) | Annually | Invitation sent to SOM / SOSJ | Tour scheduled for SOM / SOSJ | Keysbrook CCG site tour held for the Group on 5 October 2022, tour offered for new Councillors post 2023 local govt election. | 2023 | Tours offered as part of ongoing operations | | |
| 4.4 | Community Consultation Group – comprised of 8 individuals plus Doral management | Meetings held quarterly given steady state operations phase. | Yes | 2023 | Attendance at meetings, Minutes of Meeting circulated to both Shires and on Doral website. Site tour planned for 1 November 2023. | 02/11/2022 01/0/2023 03/05/2023 02/08/203 01/11/2023 | 2024 dates to be advised | | |
| 4.5 | Newsletter / letter drop | Minimum of once each 6 months | Yes | Newsletter & community updates (Nov 22, April 23, August 2023, Western Extension letter to nearest | Nearest neighbour communications sent every ~ 12 weeks. One-one- consultation / phone conversation / letter with stakeholders regarding proposed western extension and Lot 63 environmental approvals | 2023 | October 2023 newsletter in print. Next community update due Nov 2023. | | |



| 4.0 | COMMUNITY CONSULTATION FI | RAMEWORK FOR THE | KEYSBROO | K PROJECT | | | |
|---------------|--------------------------------|--|-----------------|---|--|------|----------|
| Audit Code | Assessment Task | Timing | Complian | ce | Action | | Comments |
| | | | Yes / No Date | | Action Taken | Date | |
| | | | | neighbours April 2023 | | | |
| 4.6 | Web-site updates | Ongoing | Yes | October 2023 | Newsletters uploaded, sponsorship application form and commitments, environmental management plans, CCG Minutes etc | 2023 | Ongoing |
| 4.7 | Council Briefings | Annually | | | Site | | |
| | - Shire of Murray (execs) | | Yes | Meeting held 26 April 2023 | Meeting with CEO and Planning at Council offices. | 2023 | Ongoing |
| | - Shire of SJ (execs) | | Yes | 23 February 2023 | Meeting with CEO and Planning Manager, update on northern / western extension program | 2023 | Ongoing |
| 4.8 | Local members of Parliament | Annually | No | Copies of site update letters provided. | Robyn Clarke MLA and Hugh Jones MLA – meeting confirmed for 21 Nov 2023 at Keysbrook site | 2023 | Ongoing |
| 4.9 | Meeting with community groups: | Annually and the beginning of each phase | - | | | | |
| | - Landcare State | | N/A | - | Landcare State advised it is sufficient for Doral to meet just with local Landcare groups | - | |



| 4.0 | COMMUNITY CONSULTATION FRA | AMEWORK FOR | THE KEYSBROOP | (PROJECT | | | |
|---------------|--|-------------|---------------|--|---|------|--|
| Audit Code | Assessment Task | Timing | Compliand | ce | Action | | Comments |
| | | | Yes / No | Date | Action Taken | Date | |
| | - Landcare each local authority (Landcare SJ) | | Yes | Ongoing Meeting held with new CEO in August 2023. | Ongoing community and engagement through tree planting and cockatoo nesting hollows. | 2023 | Engagement ongoing through various partnership agreements and event participation. |
| | North Dandalup and Districts Community Association | | Yes | October 2023 | Ongoing communication, request sent for meeting. | 2023 | Engagement ongoing |
| | - Peel-Harvey Catchment Forum | | No | October 2023 | Receives Keysbrook newsletter and community updates as relevant. No face to face meeting held in 2022, request sent for Nov 2023. | 2023 | Engagement ongoing. |
| | Groups in addition to Framework | | | | | | |
| | - Peel Development Commission | Annually | Yes | 2023 | Project Updates provided including Keysbrook newsletter. | 2023 | Ongoing |
| | - North Dandalup Volunteer Bush Fire Brigade | Annually | Yes | October 2023 | Invitation sent requesting site visit, awaiting confirmation. | 2023 | Ongoing |
| | Keysbrook Volunteer Bush Fire Brigade | Annually | Yes | October 2023 | Invitation sent requesting site visit, awaiting confirmation. | 2023 | Ongoing |
| 4.10 | Provide details of number and nature of complaints from the previous 12 months | Annually | Yes | October 2023 | 24/7 mobile number provided to all neighbours to call should immediate assistance be required from site – 0499 000 365, included on all updates and newsletters | 2023 | Doral Stakeholder Interaction guidelines followed for all complaints. |



| 4.0 | COMMUNITY CONSULTATION FRAMEWORK FOR THE KEYSBROOK PROJECT | | | | | | |
|---------------|--|--|----------|---------------|---|------------------|---|
| Audit Code | Assessment Task Timing Compliance | | Action | | Comments | | |
| | | | Yes / No | Date | Action Taken | Date | |
| | | | | January 2023 | Neighbour – comment sent in regard to general observation around dust, noise, light pollution and water. Meeting held with neighbour to discuss in further detail. | January 2023 | Added to community database, water bore monitored and results provided. |
| | | | | January 2023 | Neighbour – phone call to site in regard to observation of dust whilst travelling in vehicle on Hopeland Road. Matter investigated, site not operating in area at the time. | January 2023 | Advised of outcome of investigation, added to the community database, map sent of operational area and completed rehabilitation. |
| | | | | February 2023 | Neighbour – general observation around dust and impact on car in carport. During that time of year there is dust around, distance to site is significant. | February 2023 | Dust monitor checked, no non- compliance recorded at that time. Requested to keep note of dust observations. |

| SPONSORS | SHIP FOR REPORTING PERIOD | | | - |
|----------|--------------------------------------|---|-----------|-----------------|
| Date | Organisation | Event / Project | Term | Shire |
| Jan 23 | The Art Corner | Ongoing funding for art supplies | 2/3 years | Shire of Murray |
| Jan 23 | Mundijong Arts and Crafts | Wadding for quilts for women's crisis centres | 1 year | Shire of SJ |
| Feb 23 | Serpentine Food & Farm Alliance | Food and Farm Festival | 1/3 years | Shire of SJ |
| Feb 23 | Shire of Murray | Pinjarra Festival | 2/3 years | Shire of Murray |
| Feb 23 | Dwellingup Community Village | 2023 centenary hospital celebration | 1 year | Shire of Murray |
| March 23 | Serpentine Ladies Golf Club | Ladies Open Day | 1/1 year | Shire of SJ |
| March 23 | Shire of Murray | Annual school children's tree planting | 1 year | Shire of Murray |
| March 23 | Coolup Progress Association | Anzac Mural | 1 year | Shire of Murray |
| March 23 | Serpentine Lions Club | Annual log chop | 1 year | Shire of SJ |
| June 23 | Murray Historical Society | Purchase of computer for archiving purposes | 1 year | Shire of Murray |
| July 23 | Pinjarra Bowling Club | Shade shelter | 3/3 years | Shire of Murray |
| Oct 23 | Byford Carols | Byford Xmas Carols (1 Dec) | 1/3 Year | Shire of SJ |
| Oct 23 | Friends of Edenvale Inc. | Pinjarra Garden Day | 1/1 year | Shire of Murray |
| Oct 23 | Keysbrook Community Hall | Children's xmas party | Ongoing | Shire of SJ |
| | \$50,000 (period of funding, 1 Janua | ary 2023 to 31 December 2023). | | |



This page deliberately blank



ATTACHMENT

Visual Assessment of the Keysbrook Project

| Visual Assess | ment 1 | | |
|--|----------------------------|---------------------------------|----------------------------|
| Location Description railway access track | | ection of Page Road and Atkir | ns Road, along the western |
| Photo Orientation: V | Vest North West in line wi | th stone retaining wall, view a | cross Lot 105. |
| Coordinates: | MGA94 Zone 50 | 403496mE | 6408076mN |
| Date and | Description | Ph | oto |
| 28 th September 201 <u>Mining Activities Vis</u> • None | | | |
| 5 th October 2017 <u>Mining Activities Vis</u> • None | i <u>ble</u> : | | |
| 4 th October 2018 <u>Mining Activities Vis</u> • None | i <u>ble</u> : | | |

Visual Assessment 1

Location Description: 20m north of the intersection of Page Road and Atkins Road, along the western railway access track.

Photo Orientation: West North West in line with stone retaining wall, view across Lot 105.

| Coordinates: | MGA94 Zone 50 | 403496mE | 6408076mN |
|---|---------------|----------|-----------|
| | Description | Pho | |
| 2 nd October 2019 <u>Mining Activities Visible</u> • None | | | |
| 14 th October 2020 <u>Mining Activities Visible</u> • None | <u>e</u> : | | |
| 12 th October 2021 <u>Mining Activities Visibl</u> • None | <u>e</u> : | | |

Visual Assessment 1

Location Description: 20m north of the intersection of Page Road and Atkins Road, along the western railway access track.

Photo Orientation: West North West in line with stone retaining wall, view across Lot 105.

| Coordinates: | MGA94 Zone 50 | 403496mE | 6408076mN |
|---|----------------|----------|-----------|
| Date and De | escription | Ph | ioto |
| 10 th October 2022 <u>Mining Activities Vis</u> • None | i <u>ble</u> : | | |
| 13 th October 2023 <u>Mining Activities Vis</u> • None | i <u>ble</u> : | | |

Visual Assessment 2

Location Description: 300m south of the intersection of Page Road and Atkins Road, in line with the yellow underground cable post.

Photo Orientation: West in line with the Telstra yellow underground cable post, view across Lot 104.

| Coordinates: | MGA94 Zone 50 | 403428mE | 6407701mN |
|--|-----------------------------------|----------|-----------|
| Date and D | escription | Ph | oto |
| 28th September 20 <u>Mining Activities Vi</u> Glimpse of ear the trees. | | | |
| 5th October 2017 <u>Mining Activities Vi</u> Glimpse of ear the trees. | <u>sible</u> : thworks through | | |
| 4th October 2018 <u>Mining Activities Vi</u> Glimpse of per noise/visual but trees. | | | |

Visual Assessment 2

Location Description: 300m south of the intersection of Page Road and Atkins Road, in line with the yellow underground cable post.

Photo Orientation: West in line with the Telstra yellow underground cable post, view across Lot 104.

| Coordinates: | MGA94 Zone 50 | 403428mE | 6407701mN | |
|--|------------------|----------|-----------|--|
| Date and D | escription | Photo | | |
| 2nd October 2019 <u>Mining Activities Vi</u> Glimpse of per noise/visual bu trees. | | | | |
| 14 th October 2020 <u>Mining Activities Vi</u> • None. | <u>sible</u> : | | | |
| 12 th October 2021 <u>Mining Activities Vi</u> • None | <u>sible</u> : | | | |

Visual Assessment 2

Location Description: 300m south of the intersection of Page Road and Atkins Road, in line with the yellow underground cable post.

Photo Orientation: West in line with the Telstra yellow underground cable post, view across Lot 104.

| Coordinates: | MGA94 Zone 50 | 403428mE | 6407701mN |
|--|---------------|----------|-----------|
| Date and D | escription | Pho | to |
| 10 th October 2022 <u>Mining Activities Visibl</u> • None | <u>e</u> : | | |
| 13 th October 2023 <u>Mining Activities Visibl</u> • None | <u>e</u> : | | |

Visual Assessment 3

Location Description: 1.7 km south of the intersection of Page Road and Atkins Road (2.4km North of Readhead Road), in line with the gate into a cattle yard and fence corridor running east-west. Photo Orientation: West North West in line with cattle yard gate, view across Lot 300. MGA94 Zone 50 403359mE 6406305mN Coordinates: Photo **Date and Description** 28th September 2016 Mining Activities Visible: None 5th October 2017 Mining Activities Visible: MFU Noise Bund visible now clearing . on Lot 300 has been undertaken ahead of mining. Construction of perimeter bund is • evident as part of pre-mining activities. Mobile plant.

4th October 2018

Mining Activities Visible:

- Perimeter bunds
- MFU
- Mobile plant
- Some distant views of earthworks, predominantly noise/visual earthen bunds.



Visual Assessment 3

Location Description: 1.7 km south of the intersection of Page Road and Atkins Road (2.4km North of Readhead Road), in line with the gate into a cattle yard and fence corridor running east-west.

Photo Orientation: West North West in line with cattle yard gate, view across Lot 300.

| Coordinates: | MGA94 Zone 50 | 403359mE | 6406305mN |
|---|------------------|----------|-----------|
| Date and D | escription | Ph | oto |
| 2nd October 2019 <u>Mining Activities Visibl</u> Perimeter bunds Some distant view predominantly nois bunds. | s of earthworks, | | |
| 14 th October 2020 <u>Mining Activities Visibl</u> • None | <u>e</u> : | | |
| 12 th October 2021 <u>Mining Activities Visibl</u> • None | <u>e</u> : | | |

Visual Assessment 3

Location Description: 1.7 km south of the intersection of Page Road and Atkins Road (2.4km North of Readhead Road), in line with the gate into a cattle yard and fence corridor running east-west.

Photo Orientation: West North West in line with cattle yard gate, view across Lot 300.

| Coordinates: | MGA94 Zone 50 | 403359mE | 6406305mN |
|---|---------------|----------|-----------|
| Date and D | escription | Photo | |
| 10 th October 2022 <u>Mining Activities Visit</u> • None | <u>lle</u> : | | |
| 13 th October 2023 <u>Mining Activities Visit</u> • None | l <u>e</u> : | | |

Visual Assessment 4

Location Description: Intersection of Readhead road and McMahon Road, looking north along the powerline corridor. Photo Orientation: North in line with street sign, view across Lot 5. Coordinates: MGA94 Zone 400068mE 6403807mN 50 **Date and Description** Photo 28th September, 2016 Mining Activities Visible: None 5th October 2017 Mining Activities Visible: None . 4th October 2018 Mining Activities Visible: None •

Visual Assessment 4

Location Description: Intersection of Readhead road and McMahon Road, looking north along the powerline corridor.

Photo Orientation: North in line with street sign, view across Lot 5.

| Coordinates: | MGA94 Zone 50 | 400068mE | 6403807mN | |
|--|------------------|----------|-----------|--|
| Date and | Description | Photo | | |
| bund is | | | | |
| 14 th October 202 <u>Mining Activities</u> • None | | | | |
| 12 th October 202 <u>Mining Activities</u> | | | | |

Visual Assessment 4

Location Description: Intersection of Readhead road and McMahon Road, looking north along the powerline corridor. Photo Orientation: North in line with street sign, view across Lot 5. Coordinates: MGA94 Zone 50 400068mE 6403807mN **Date and Description** Photo 10th October 2022 Mining Activities Visible: None. 13th October 2023 Mining Activities Visible: None.



Visual Assessment 5

<u>Location Description</u>: South western corner of Lot 62 at access gate located on Hopelands Road. <u>Photo Orientation</u>: North east in line with gate, view across Lot 62.

| Coordinates: | MGA94 Zone 50 | 397628mE | 6405402mN |
|---|-----------------------|----------|-----------|
| Date and Description | | Photo | |
| 28 th September 2016 <u>Mining Activities Visible</u> : None. | | | |
| | | | |
| 5 th October 2017 | | | |
| Mining Activities Vi | <u>isible</u> : None | | |
| 4 th October 2018 | | | |
| Mining Activities Vi | i <u>sidie</u> : None | | |

Visual Assessment 5

<u>Location Description</u>: South western corner of Lot 62 at access gate located on Hopelands Road. <u>Photo Orientation</u>: North east in line with gate, view across Lot 62.

| Coordinates: | MGA94 Zone 50 | 397628mE | 6405402mN |
|---|--------------------|----------|----------------|
| Date and Description | | Photo | |
| 2 nd October 2019 <u>Mining Activities Visible</u> : None | | | |
| 14 th October 2020 | | | |
| Mining Activities Vis | <u>ioie</u> . None | | |
| 12 th October 2021 Mining Activities Visi | ible: None. | - | and the second |
| | | | |

Visual Assessment 5

<u>Location Description</u>: South western corner of Lot 62 at access gate located on Hopelands Road. <u>Photo Orientation</u>: North east in line with gate, view across Lot 62.

| Coordinates: | MGA94 Zone 50 | 397628mE | 6405402mN |
|--|---------------|----------|-----------|
| Date and Description | | Photo | |
| 10 th October 2022 <u>Mining Activities Visible</u> : None. | | | |
| 13 th October 2023 <u>Mining Activities Visible</u> : None. | | | |

Visual Assessment 6

<u>Location Description</u>: Approximately 5m south of the driveway into Lot 63 along Hopelands Road. <u>Photo Orientation</u>: East South East looking towards the WCP, view across Lot 63.

| Coordinates: | MGA94 Zone 50 | 397602mE | 6407680mN |
|--|--------------------|----------|-----------|
| Date and Description | | Photo | |
| 28th September 2016 <u>Mining Activities Visible</u>: Wet Concentrator Plant Workshop pre-mining workings mobile plant | | | |
| 5 th October 2017 <u>Mining Activities Vis</u> • Wet Concer • Workshop • Perimeter b | ntrator Plant | | |
| 4th October 2018 <u>Mining Activities Vis</u> Glimpses through tr Wet Concentrat Workshop Perimeter bunds | ees of or Plant | | |

| Visual Assessment 6 | | | | |
|--|--|--|--|--|
| Location Description: Approximately 5m south of the driveway into Lot 63 along Hopelands Road. | | | | |
| Photo Orientation: East South East | Photo Orientation: East South East looking towards the WCP, view across Lot 63. | | | |
| Coordinates: MGA94 Zone | 50 397602mE 6407680mN | | | |
| Date and Description | Photo | | | |
| 2 nd October 2019 | | | | |
| Mining Activities Visible: | | | | |
| Glimpses through trees of | | | | |
| Wet Concentrator PlantWorkshop | A CONTRACTOR OF THE OWNER OF THE | | | |
| Perimeter bunds | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| 14 th October 2020 | and the second s | | | |
| Mining Activities Visible: | | | | |
| Glimpses through trees ofWet Concentrator Plant | 1 de | | | |
| Workshop | | | | |
| Perimeter bunds | | | | |
| | and a second state of the | | | |
| | | | | |
| | 1 NUE VANS | | | |
| | the state of the s | | | |
| 12 th October 2021 | | | | |
| Mining Activities Visible: | 244 | | | |
| Glimpses through trees of | | | | |
| Wet Concentrator Plant | | | | |
| WorkshopPerimeter bunds | | | | |
| | | | | |
| | | | | |
| | | | | |
| | The state of the second s | | | |
| | | | | |
| | いいは、「「「「「「「「」」」」で、「「「」」」、「「」」、「」」、「」」、「」」、「 | | | |

Visual Assessment 6 Location Description: Approximately 5m south of the driveway into Lot 63 along Hopelands Road. Photo Orientation: East South East looking towards the WCP, view across Lot 63. Coordinates: MGA94 Zone 50 397602mE 6407680mN **Date and Description** Photo 10th October 2022 Mining Activities Visible: Glimpses through trees of Wet Concentrator Plant Workshop Perimeter bunds 13th October 2023 Mining Activities Visible: Glimpses through trees of Wet Concentrator Plant Workshop Perimeter bunds

•

•

.

| Visual Assessment 7 | | | | |
|---|--------------------|--------------------|-----------------------------|--------|
| Location Descriptio | n: North west acc | ess ga | ate to Lot 63 off Hopelands | Road. |
| Photo Orientation: | South west in line | with a | access gate, view across Lo | ot 63. |
| Coordinates: | MGA94 Zone 50 | 397595mE 6408614mN | | |
| Date and De | escription | | Phe | oto |
| 28 th September 20 rd Mining Activities Vis • pre-mining • mobile plan | sible: | | | |
| 5th October 2017 <u>Mining Activities Visible</u>: Perimeter bunds Early stage rehabilitation works | | | | |
| 4 th October 2018 <u>Mining Activities Vis</u> Glimpses of pe through the trees. | | | | |

| Visual Assessment 7 | | | |
|---|--|-----------|--|
| Location Description: North west access gate to Lot 63 off Hopelands Road. Photo Orientation: South west in line with access gate, view across Lot 63. | | | |
| Coordinates: MGA94 Zone 50 | 397595mE | 6408614mN | |
| Date and Description | Ph | oto | |
| 2 nd October 2019 | | | |
| Mining Activities Visible: | And and a state of the state of | | |
| Glimpses of perimeter bunds through the trees. | | | |
| 14 th October 2020 | | | |
| Mining Activities Visible: • Occasional traffic using access road | | | |
| 12th October 2021 <u>Mining Activities Visible</u>: Occasional traffic using access road | | | |

Visual Assessment 7 Location Description: North west access gate to Lot 63 off Hopelands Road. Photo Orientation: South west in line with access gate, view across Lot 63. MGA94 Zone 50 Coordinates: 397595mE 6408614mN Photo **Date and Description** 25th October 2022 Mining Activities Visible: Occasional traffic using access road 13th October 2023 Mining Activities Visible: Occasional traffic using access road

| Visual Asses | Visual Assessment 8 | | | | | |
|---|---|-------------------------------------|-----------|--|--|--|
| Location Descript | ion: Along Elliot | t Road, 1km west of the railway lir | ne. | | | |
| Photo Orientation | Photo Orientation: South west, view across Lot 1. | | | | | |
| Coordinates: | MGA94 Zone 50 | 402791mE | 6410278mN | | | |
| Date and De | escription | Pł | noto | | | |
| 28 th September 2 | | | | | | |
| 5 th October 2017 <u>Mining Activities M</u> • MFU Nois • Early stag rehabilita | se Bund | | | | | |
| 4th October 2018 Mining Activities V MFU noise bu Rehabilitation (pasture) Perimeter bur Mobile plant | und works | | | | | |

| Visual Asses | Visual Assessment 8 | | | | | |
|---|---|----------|-----------|--|--|--|
| Location Description: Along Elliott Road, 1km west of the railway line. | | | | | | |
| Photo Orientation: | Photo Orientation: South west, view across Lot 1. | | | | | |
| Coordinates: | MGA94 Zone 50 | 402791mE | 6410278mN | | | |
| Date and De | scription | Pl | hoto | | | |
| 2nd October 2019 <u>Mining Activities V</u> Rehabilitation (pasture) Perimeter bun | works | | | | | |
| 14th October 2020 <u>Mining Activities V</u> Rehabilitation (pasture) Perimeter bun | works | | | | | |
| 12th October 2021 <u>Mining Activities V</u> Rehabilitation (pasture) Perimeter bun | works | | | | | |

| Visual Asses | Visual Assessment 8 | | | | |
|--|----------------------------|----------|-----------|--|--|
| Location Description: Along Elliott Road, 1km west of the railway line. Photo Orientation: South west, view across Lot 1. | | | | | |
| Coordinates: | MGA94 Zone 50 | 402791mE | 6410278mN | | |
| Date and De | scription | Pr | noto | | |
| 10th October 2022 <u>Mining Activities Visible</u>: Rehabilitation works (pasture) Perimeter bunds | | | | | |
| 13th October 2023 <u>Mining Activities V</u> Rehabilitation (pasture) Perimeter bun | / <u>isible</u> : works | | | | |

| Visual Assessment 9 | | | | |
|--|-------|--------------------|--|--|
| Location Description: Southern end of Wescott Road. Photo Orientation: South west in line with access gate, view across Lot 6. | | | | |
| Coordinates: MGA94 Zor | ne 50 | 401635mE 6407852mN | | |
| Date and Description | | Photo | | |
| 28 th September 2016 <u>Mining Activities Visible</u> : • Topsoil windrows • Early stage rehabilitation works | | | | |
| 5 th October 2017 <u>Mining Activities Visible</u> : • Topsoil windrows • Rehabilitation works | | | | |
| 4th October 2018 <u>Mining Activities Visible</u>: Newly rehabilitated pasture Topsoil windrows Mobile plant (rehabilitation equipment) Rehabilitation works | | | | |

| Visual Assessment 9 | | | | |
|---|----------|-----------|--|--|
| Location Description: Southern end of Wescott Road. | | | | |
| Photo Orientation: South west in line with a | | | | |
| Coordinates: MGA94 Zone 50 | 401635mE | 6407852mN | | |
| Date and Description | Phot | to | | |
| 2nd October 2019 <u>Mining Activities Visible</u>: Newly rehabilitated pasture Topsoil windrows Mobile plant (rehabilitation equipment) 14th October 2020 <u>Mining Activities Visible</u>: | | | | |
| Newly rehabilitated pasture | | | | |
| 12th October 2021 <u>Mining Activities Visible</u>: Newly rehabilitated pasture | | | | |

| Visual Assessment 9 | | | | |
|--|----------|-----------|--|--|
| <u>Location Description</u> : Southern end of Wescott Road. <u>Photo Orientation</u> : South west in line with access gate, view across Lot 6. | | | | |
| Coordinates: MGA94 Zone 50 | 401635mE | 6407852mN | | |
| Date and Description | Pł | noto | | |
| 10th October 2022 <u>Mining Activities Visible</u>: Rehabilitated pasture Profiling works as per landowners request. Native Revegetation Shelter Belts[AT | 1] | | | |
| 13th October 2023 <u>Mining Activities Visible</u>: Rehabilitated pasture Profiling works as per landowners request. Native Revegetation Shelter Belts[AT | 2] | | | |

| Visual Assess | ment 10 | | | |
|--|--------------------------|------------------|-----------------------------|--------------------|
| Location Description | : Southern end of Wes | scc | ott Road. | |
| Photo Orientation: S | outh east in line with a | acc | ess gate, view across Lot 1 | 13. |
| Coordinates: | MGA94 Zone 50 | | 401635mE | 6407850mN |
| Date and I | Description | | Ph | oto |
| 28 th September 2010 | 6 | | | |
| Mining Activities Visi | i <u>ble</u> : None | | | |
| | | | Sec. 2 | . 191 |
| | | | the second | in the |
| | | | | - |
| | | | | |
| | | | | |
| | | | | |
| | | | The second | All and a second |
| 5 th October 2017 | | | | |
| Mining Activities Visi | ible: | | | |
| Perimeter bi | | | | - |
| | | | Contraction of the second | |
| | | | Are the | Alle Alle |
| | | | - Contraction of the second | |
| | | | The state of | |
| | | | | |
| | | | | |
| | | $\left \right $ | | |
| 4 th October 2018 Mining Activities Visi | ible [.] | | and the second | |
| Perimeter bund | <u>.</u> | | | |
| | | | Contraction of the second | 1 |
| | | | A CAL | ALL CAL |
| | | | | |
| | | | | |
| | | | | A STATE OF A STATE |
| | | | | |
| | | | The Mark | |

| Visual Assessment 10 | |
|---|--|
| Location Description: Southern end of Wes | scott Road. |
| Photo Orientation: South east in line with a | access gate, view across Lot 113. |
| Coordinates: MGA94 Zone 50 | 401635mE 6407850mN |
| Date and Description | Photo |
| 2nd October 2019 <u>Mining Activities Visible</u>: Newly rehabilitated pasture Topsoil windrows | |
| Mobile plant (rehabilitation equipment) Rehabilitation works | |
| 14 th October 2020 | |
| Mining Activities Visible: | |
| Newly rehabilitated pasture | |
| | |
| 12 th October 2021 | |
| Mining Activities Visible: | and the second |
| Newly rehabilitated pasture | |
| | Martin and an and the |
| | |

| Visual Assessment 10 | | | | |
|---|----------------------|--|--|--|
| Location Description: Southern end of Wescott Road. Photo Orientation: South east in line with access gate, view across Lot 113. | | | | |
| Coordinates: MGA94 Zone 5 | 0 401635mE 6407850mN | | | |
| Date and Description | Photo | | | |
| 10 th October 2022 <u>Mining Activities Visible</u> : • Rehabilitated pasture | | | | |
| 13th October 2023 <u>Mining Activities Visible</u>: Rehabilitated pasture | | | | |

| Visual Assessment 11 | Visual Assessment 11 | | | |
|---|--|--|--|--|
| Location Description: 800m south alo the western side of the road. | ong Wescott Road (from the intersection with Elliott Road), on | | | |
| Photo Orientation: South west, view | across Lot 57. | | | |
| Coordinates: MGA94 Zone 5 | 50 401617mE 6409410mN | | | |
| Date and Description | Photo | | | |
| 28th September 2016 <u>Mining Activities Visible</u>: MFU Wet Concentrator Plant Mobile plant (PC1250) | | | | |
| 5 th October 2017 <u>Mining Activities Visible</u> : • Wet Concentrator Plant | | | | |
| 4th October 2018 <u>Mining Activities Visible</u>: Wet Concentrator Plant | | | | |

Visual Assessment 11

Location Description: 800m south along Wescott Road (from the intersection with Elliott Road), on the western side of the road.

Photo Orientation: South west, view across Lot 57.

| Coordinates: | MGA94 Zone 50 | 401617mE | 6409410mN |
|---|---------------|----------|-----------|
| Date and Description | | Photo | |
| 2nd October 2019 <u>Mining Activities Visible</u>: MFU noise bund Rehabilitation works (pasture) Perimeter bunds Mobile plant | | | |
| 14th October 2020 <u>Mining Activities Vi</u> Rehabilitation Perimeter bund Mobile plant | works | | |
| 12th October 2021 <u>Mining Activities Vi</u> Rehabilitation v Perimeter bund | works | | |

Visual Assessment 11

Location Description: 800m south along Wescott Road (from the intersection with Elliott Road), on the western side of the road.

Photo Orientation: South west, view across Lot 57.

| Coordinates: | MGA94 Zone 50 | 401617mE | 6409410mN | |
|--|---------------|----------|-----------|--|
| Date and Description | | Photo | | |
| 10th October 2022 <u>Mining Activities Visible</u>: Rehabilitation works Perimeter bunds | | | | |
| 13th October 2023 <u>Mining Activities Visible</u>: Rehabilitation works | | | | |

Visual Assessment 11A

Location Description: 800m south along Wescott Road (from the intersection with Elliott Road), on the western side of the road.

Photo Orientation: South east down Wescott Road, view across Lot 52.

| Coordinates: | MGA94 Zone 50 | 401617mE | 6409410mN |
|--|------------------------------------|----------|-----------|
| Date and Description | | Photo | |
| 5 th October 2017 Mining Activities Vi • Early stage works | <u>sible</u> : e rehabilitation | | |
| 4th October 2018 <u>Mining Activities Vi</u> Rehabilitation v | <u>sible</u> : vorks (pasture) | | |
| 2nd October 2019 <u>Mining Activities Vi</u> Rehabilitation v | <u>sible</u> : vorks (pasture) | | |

Visual Assessment 11A

Location Description: 800m south along Wescott Road (from the intersection with Elliott Road), on the western side of the road.

Photo Orientation: South east down Wescott Road, view across Lot 52.

| Coordinates: | MGA94 Zone 50 | 401617mE | 6409410mN |
|--|---------------|----------|-----------|
| Date and Description | | Photo | |
| 14th October 2020 <u>Mining Activities Visi</u> Rehabilitation wood in the second s | | | |
| 12th October 2021 <u>Mining Activities Visi</u> Rehabilitation wo | | | |
| 10 th October 2022 <u>Mining Activities Visi</u> • Rehabilitation wo | | | |

Visual Assessment 11A

Location Description: 800m south along Wescott Road (from the intersection with Elliott Road), on the western side of the road.

Photo Orientation: South east down Wescott Road, view across Lot 52.

| Coordinates: | MGA94 Zone 50 | 401617mE | 6409410mN |
|--|---------------|----------|-----------|
| Date and Description | | Photo | |
| 13th October 2023 <u>Mining Activities Visi</u> Rehabilitation we | | | |

Visual Assessment 12

Location Description: Along Elliott Road 800m west of the Wescott Road intersection under the high voltage power lines.

Photo Orientation: South in line with SEC gate, view across Lot 57.

| Coordinates: | MGA94 Zone 50 | 400793mE | 6410255mN |
|--|------------------------------------|----------|--|
| Date and Description | | Photo | |
| 28 th September 2016 <u>Mining Activities Visi</u> <u>distance</u>): • Wet Concer • Pre-mining a | <u>ble (in the</u> trator Plant | | |
| 5 th October 2017 <u>Mining Activities Visited istance</u>): • Wet Concern • Pre-mining a | trator Plant | | SEC |
| 4th October 2018 <u>Mining Activities Visi</u> Wet Concentrate Pre-mining area | or Plant | | SECTION OF CONTRACTOR OF CONTRAC |

Visual Assessment 12

Location Description: Along Elliott Road 800m west of the Wescott Road intersection under the high voltage power lines.

Photo Orientation: South in line with SEC gate, view across Lot 57.

| Coordinates: | MGA94 Zone 50 | 400793mE | 6410255mN |
|---|----------------|----------|-----------|
| Date and Description | | Photo | |
| 2nd October 2019 <u>Mining Activities Visi</u> Wet Concentrato Pre-mining area | | | |
| 14th October 2020 <u>Mining Activities Visi</u> MFU noise bund Rehabilitation we Perimeter bunds Mobile plant | orks (pasture) | | |
| 12th October 2021 <u>Mining Activities Visi</u> MFU noise bund Rehabilitation we Perimeter bunds Mobile plant | orks (pasture) | | |

Visual Assessment 12

Location Description: Along Elliott Road 800m west of the Wescott Road intersection under the high voltage power lines.

Photo Orientation: South in line with SEC gate, view across Lot 57.

| Coordinates: | MGA94 Zone 50 | 400793mE | 6410255mN |
|---|---------------|----------|-----------|
| Date and Description | | Photo | |
| 10 th October 2022 <u>Mining Activities Visible</u> : • Perimeter Bund • Noise Bund | | | |
| 13 th October 2023 <u>Mining Activities Visible</u> : | | | |
| Noise Bund Mining activit Dust Crops | | | |

